



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3914-041
Job Sheet 182164



Part No: D3914-041

Job Qty: 1 ea

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 8/20/18

Job Tracking No:

Due Date: 9/7/18

Created By: Jason Leroux

Type: Stock

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	9/7/18	9/7/18	0.00	0.00	Start Up Large Fab-5		BC 2017-08-25
100	Large Fab	1 pcs	9/7/18	9/7/18	0.00	0.07	Large Fab 1		2017-08-27
110	QC	1 pcs	9/7/18	9/7/18	0.00	0.00	QC9		
120	QC	1 pcs	9/7/18	9/7/18	0.00	0.00	QC5		
130	Powdercoat	1 pcs	9/7/18	9/7/18	0.00	0.40	Powdercoat4		BR 18-9-6
135	QC	1 pcs	9/7/18	9/7/18	0.00	0.00	QC3		M 18-9-6
140	HandFinish	1 pcs	9/7/18	9/7/18	0.00	0.80	HandFinish3		M 18-9-6
150	QC	1 pcs	9/7/18	9/7/18	0.00	0.00	QC3		AK 18-9-6
160	Packaging	1 pcs	9/7/18	9/7/18	0.00	0.00	Packaging3-2		
170	QC21-SA	1 Ea	9/7/18	9/7/18	0.00	0.00	QC21		CR 18.09.06

Part Op 100 - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld hinge (3) and Mounting brackets as per dwg
Descriptions: D3914 ***Visual inspect before welding mesh*** 3- tack weld mesh on basket as per dwg D3914 ***Cut out mesh where
label plate goes in center off basket lid as per dwg D4020-5. Make sure to place mesh correctly on lid, check with label
plate before tacking mesh***

130 - *** mask sides of hinge prior to powdercoat***

140 - 1- Mask data plate and apply wing walk on outside surface of mesh as per dwg 2- install label as per dwg ***Mask
label plate to size of label, use scotchbrite red pad to lightly sand area for label, apply label***

M/38839 START: 10:50 CNT: 320° FINISH: 11:00

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 Ea (2 ea)	90-Start up Operation	3078989
D3914-1	Rib	2 Ea (2 ea)	90-Start up Operation	3090026
D3914-7	Rib	2 Ea (2 ea)	90-Start up Operation	3089308
D4016-3	Hinge Half, Lid	3 Ea (3 ea)	90-Start up Operation	3088888
D4018-5	Rib	9 Ea (9 ea)	90-Start up Operation	3088888
D4020-5	Mesh (350 Basket Long, Lid)	1 Ea (1 ea)	90-Start up Operation	3003452
D4021-3	Data Plate	1 Ea (1 ea)	90-Start up Operation	3064261
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 Ea (2 ea)	90-Start up Operation	3016663

Job Allocations				
Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D2581	2	73	0
	D3914-1	2	15	0
	D3914-7	2	10	0
	D4016-3	3	9	0
	D4018-5	9	30	0
	D4020-5	1	0	0
	D4021-3	1	17	0
	D4035-043	2	5	0
Part Specifications				
Specifications could not be found.				

Plex 8/20/18 10:47 AM dart.leroux.jason

Master Unit 005



Job No

1821



Container No: S105578



Part: D3914-041

Job No: 182164

Serial No/Batch: S105578

Revision: A/D

Inspector:

Exp Date:

Instructions: Various STC's

Dart Aerospace Ltd.
1270 Aberdeen Street
Howkesbury, ON K64 1K7
CANADA
TEL.: 1 613 632-6200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 08/27/18